



WINTER – 19 EXAMINATION

Subject Name: EME

Model Answer

Subject Code:

22342

Important Instructions to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more Importance (Not applicable for subject English and Communication Skills).
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgement on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.


| Q. No. | Sub Q. N. | Answer | Marking Scheme |
|--------|-----------|--|--|
| Q.1 | a) | Types of Metrology:- 1) Legal metrology 2) Scientific Metrology 3) Industrial metrology | 01 Mark Each Any Two |
| | b) | Mechanical Comparator A)Dial Indicator B)Johansson Mikrokator C)Sigma Comparator D) Mechanical optical comparator <i>Any one sketch for 1M</i> | List 01 Mark Sketch OF ANY ONE 01 Mark |
| | c) | Taylors Principle of Gauge design:- 1) GO gauge should be designed to check the maximum material limit, while the NO-GO gauge should be designed to check the minimum material limit. 2) GO gauges should check all the related dimensions (roundness, size, location ect). Simultaneously whereas NO-GO gauge should check only one element of the dimension at a time. | 01 Mark Each |
| | d) | Backlash error : Backlash is the play between the mating tooth surfaces i.e the distance through which a gear can be rotated to bring its non working flank in contact to the teeth of the mating gear. Run out error : It is the total range of the readings of a fixed indicator with contact point applied to a surface rotated , without axial movement about a fixed axis . Run out error is related to concentricity of gear outer diameter with mounting hole. | 01 Mark Each |

OUR CENTERS :

KALYAN | DOMBIVLI | THANE | NERUL | DADAR
Contact - 9136008228

Page No: ____ / N





| e) | For Measuring acute angle and obtuse angle, For checking a 'V' block: | 01 Mark Each | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|-----------------------------|--------------|---|--|--------------------------------|--------------------------------|--|--------------------------------------|------------------------------------|--|---------------------------------------|-----------------------------------|----------------|-----------------|-------------------------------|------------------------------------|--|----------------------|----------------|---------------|------------------------------|-----------------------------------|--|--|-----------------------------|
| f) | <p>(i) Primary texture : Irregularities of small wavelength are called primary texture. These are generally caused due to cutting tools, friction, wear etc., it is also termed as roughness.</p> <p>(ii) Secondary texture : Irregularities of considerable wavelength are called secondary texture, also called as waviness. These are generally caused due to misalignments, non linear feed motions, generally due to problems in machine tools</p>  | 01 Mark Each | | | | | | | | | | | | | | | | | | | | | | | | |
| g) | <p>Causes of surface roughness:-</p> <p>Vibrations, material of the work piece, type of machining, rigidity of the system consisting of machine tool, fixtures, cutting tool and work, type form material and sharpness of the cutting tool, cutting conditions (speed, feed and depth of cut), type of coolant used</p> | 02 Mark Any Four | | | | | | | | | | | | | | | | | | | | | | | | |
| Q.2 | Attempt any THREE of the following | | | | | | | | | | | | | | | | | | | | | | | | | |
| a) | <p>Needs of the inspection in manufacturing industry:-</p> <ol style="list-style-type: none"> 1) To ensure that the part, material or a component confirms to the established standard. 2) To meet the interchangeability of manufacturer. 3) To maintain the customer relation by ensuring that no faulty product reaches the customer. 4) Provide the means of finding out shortcomings in manufacture. 5) It helps to purchase good quality of raw material, tools, equipment which governs the quality of the finished product. 6) It helps to coordinate the functions of quality control, production, purchasing and other departments of the organization. 7) To take decision on the defective parts. | 01 Mark Each Any Four | | | | | | | | | | | | | | | | | | | | | | | | |
| b) | <table border="1"> <thead> <tr> <th data-bbox="305 1339 831 1377">Line Standard</th> <th data-bbox="831 1339 1302 1377">End Standard</th> </tr> </thead> <tbody> <tr> <td data-bbox="305 1377 831 1478">When length is express as distance between two parallel line is called line standard.</td> <td data-bbox="831 1377 1302 1478">When length is expressed as distance between two parallel faces is called as end standard.</td> </tr> <tr> <td data-bbox="305 1478 831 1516">Measurement is quick and easy.</td> <td data-bbox="831 1478 1302 1516">Measurement is time consuming.</td> </tr> <tr> <td data-bbox="305 1516 831 1554">It is not used for précised measurement.</td> <td data-bbox="831 1516 1302 1554">It is used for précised measurement.</td> </tr> <tr> <td data-bbox="305 1554 831 1591">It is subjected to parallax error.</td> <td data-bbox="831 1554 1302 1591">It is not subjected to parallax error.</td> </tr> <tr> <td data-bbox="305 1591 831 1629">It is not subjected to wear and tear.</td> <td data-bbox="831 1591 1302 1629">It is subjected to wear and tear.</td> </tr> <tr> <td data-bbox="305 1629 831 1667">It is cheaper.</td> <td data-bbox="831 1629 1302 1667">It is costlier.</td> </tr> <tr> <td data-bbox="305 1667 831 1705">It is simple in construction.</td> <td data-bbox="831 1667 1302 1705">It is complicated in construction.</td> </tr> <tr> <td data-bbox="305 1705 831 1789">No skilled worker is required for measurement.</td> <td data-bbox="831 1705 1302 1789">It is very accurate.</td> </tr> <tr> <td data-bbox="305 1789 831 1827">Less accurate.</td> <td data-bbox="831 1789 1302 1827">More accurate</td> </tr> <tr> <td data-bbox="305 1827 831 1864">Ex. Scale, meter tape, yard.</td> <td data-bbox="831 1827 1302 1864">Micro meter, Vernier, slip gauges</td> </tr> <tr> <td data-bbox="305 1864 831 1986"></td> <td data-bbox="831 1864 1302 1986"></td> </tr> </tbody> </table> | Line Standard | End Standard | When length is express as distance between two parallel line is called line standard. | When length is expressed as distance between two parallel faces is called as end standard. | Measurement is quick and easy. | Measurement is time consuming. | It is not used for précised measurement. | It is used for précised measurement. | It is subjected to parallax error. | It is not subjected to parallax error. | It is not subjected to wear and tear. | It is subjected to wear and tear. | It is cheaper. | It is costlier. | It is simple in construction. | It is complicated in construction. | No skilled worker is required for measurement. | It is very accurate. | Less accurate. | More accurate | Ex. Scale, meter tape, yard. | Micro meter, Vernier, slip gauges | | | 01 Mark Each Any Four |
| Line Standard | End Standard | | | | | | | | | | | | | | | | | | | | | | | | | |
| When length is express as distance between two parallel line is called line standard. | When length is expressed as distance between two parallel faces is called as end standard. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Measurement is quick and easy. | Measurement is time consuming. | | | | | | | | | | | | | | | | | | | | | | | | | |
| It is not used for précised measurement. | It is used for précised measurement. | | | | | | | | | | | | | | | | | | | | | | | | | |
| It is subjected to parallax error. | It is not subjected to parallax error. | | | | | | | | | | | | | | | | | | | | | | | | | |
| It is not subjected to wear and tear. | It is subjected to wear and tear. | | | | | | | | | | | | | | | | | | | | | | | | | |
| It is cheaper. | It is costlier. | | | | | | | | | | | | | | | | | | | | | | | | | |
| It is simple in construction. | It is complicated in construction. | | | | | | | | | | | | | | | | | | | | | | | | | |
| No skilled worker is required for measurement. | It is very accurate. | | | | | | | | | | | | | | | | | | | | | | | | | |
| Less accurate. | More accurate | | | | | | | | | | | | | | | | | | | | | | | | | |
| Ex. Scale, meter tape, yard. | Micro meter, Vernier, slip gauges | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |




OUR CENTERS :

KALYAN | DOMBIVLI | THANE | NERUL | DADAR

Contact - 9136008228

Page No: ____ / N






| | | | | | | | | | | | |
|---|--|---|---|------------------------------------|---|--|-------------------------------|----------------------------------|--|--|---|
| | b) | <p>Least count = (smallest division on main scale) / (total no. of divisions on vernier scale)</p> <p align="center">= 0.1/10 = 0.01 cm</p> <p>Total reading = (MSR) + (VSR* LC)</p> <p align="center">= (2.6) + (7*0.01)</p> <p align="center">= 2.67 cm</p> | <p>Calculations L.C 02 marks TR 02 marks</p> | | | | | | | | |
| | c) | <p>Mechanical comparator : it works on the principle of converting linear movement into angular using different mechanical linkages. It uses gears for magnification, scale pointer or digital display as indicating device. One of the most commonly used mechanical comparator is a dial indicator</p>  | <p>Working Principle 2 marks Sketch 02 marks</p> | | | | | | | | |
| | d) | <table border="1"> <tr> <td align="center">Hole basis Hole size constant</td> <td align="center">Shaft basis Shaft size constant</td> </tr> <tr> <td align="center">Represented by capital alphabets as per ISO system.</td> <td align="center">Represented by small alphabets as per ISO system</td> </tr> <tr> <td align="center">Preferred for mass production</td> <td align="center">Preferred for special production</td> </tr> <tr> <td align="center">Needs precise shaft manufacturing machines</td> <td align="center">Needs precise boring / hole manufacturing machines</td> </tr> </table> | Hole basis Hole size constant | Shaft basis Shaft size constant | Represented by capital alphabets as per ISO system. | Represented by small alphabets as per ISO system | Preferred for mass production | Preferred for special production | Needs precise shaft manufacturing machines | Needs precise boring / hole manufacturing machines | <p>Any 04 points , 01 mark each</p> |
| Hole basis Hole size constant | Shaft basis Shaft size constant | | | | | | | | | | |
| Represented by capital alphabets as per ISO system. | Represented by small alphabets as per ISO system | | | | | | | | | | |
| Preferred for mass production | Preferred for special production | | | | | | | | | | |
| Needs precise shaft manufacturing machines | Needs precise boring / hole manufacturing machines | | | | | | | | | | |
| Q.4 | a) | <p>Slip gauge accessories may listed as follows :</p>  | <p>Use 01 mark each Sketch 01 mark each any two</p> | | | | | | | | |



Measuring jaws and scribers are used for

1. Calibration of Vernier Caliper, Micrometer and Vernier Height gauge
2. For inspection in tool room and machine shops
3. Precision marking

| | | |
|----|---|---|
| b) | <p>Given data</p> <p>Shaft 30.00 -0.005 -0.018</p> <p>Hole 30.00 $+0.020$ -0.000</p> <p>$(UL)_{shaft} = 29.995$ $(LL)_{shaft} = 29.982$</p> <p>$(UL)_{hole} = 30.020$ $(LL)_{hole} = 30.000$</p> <p>Basic size Shaft = 29.982 Hole = 30.000</p> <p>Shaft and Hole tolerance</p> <p>Shaft tol = $29.995 - 29.982 = 0.013$</p> <p>Hole tol = $30.020 - 30.000 = 0.020$</p> <p>maximum clearance</p> <p>$(UL)_{hole} - (LL)_{shaft}$ $= 30.020 - 29.982$ $= 0.038$</p> <p>Minimum clearance</p> <p>$(LL)_{hole} - (UL)_{shaft}$ $= 30.000 - 29.995$ $= 0.0249$</p> | <p>Basic size 01 ,</p> <p>Tolerance 01,</p> <p>maximum clearance 01,</p> <p>Minimum clearance 01</p> <p>marks</p> |
|----|---|---|

| | | | |
|-----|----|--|--|
| | c) |  <p>(a) Diagram illustrating basic size deviations and tolerances.</p> <p>(b) Simplified schematic diagram of clearance fit.</p> | 04 marks 01 for each |
| | d) |  | Calculations 02, sketch 02 |
| | e) |  | Any of these sketch 04 marks |
| Q.5 | a) | <p>Parkinson's Gear Tester</p>  <p>FULLY SATISFACTORY MODERATE UNSATISFACTORY</p>  <p>(1) (2) (3)</p> <p>The procedure of this Parkinson's gear tester is to mount a standard gear on a fixed vertical spindle and the gear to be tested on another similar spindle mounted on a sliding carriage, maintaining the gears in mesh by spring pressure. Movements of the sliding carriage as the gears are rotated and indicated by a dial indicator, and these variations are a measure of any irregularities in the gear under test, alternatively a recorder can be fitted, in the form of a waxed circular chart and records made of the gear variation in accuracy of mesh.</p> <p>The gears are mounted on the two mandrels, so that they are free to rotate without measurable clearance. The left spindle can be moved along the table and clamped in any desired position. The right mandrel slide is free to move on steel balls, against spring pressure</p> | 03 Marks for procedure and 03 Marks for Sketch |

and it has a limited movement. The two mandrels can be adjusted so that their axial distance is equal to the designed gear centre distance.

When the waxed paper recorder is fitted, the chart makes a revolution for each one of the gears mounted on the sliding carriage. As the chart moves and rotates, the line traced records the movements of floating carriage. A circle is drawn at the same time as the record .

**** (Parkinson's Gear Tester is used to measure gear attributes and it's rolling test ,and not used for measurement of gear tooth thickness. However If students attempts this question with above solution ,the procedure and sketch of it may be considered and then appropriate marks. ..considering 03 marks for sketch and 03 marks for explanation). ****

b) Measurement of minor diameter by using floating carriage micrometer: The minor diameter is measured by a comparative method by using floating carriage diameter measuring machine and small V pieces which make contact with the root of the thread. These V pieces are made in several sizes, having suitable radii at the edges. V pieces are made of hardened steel. The floating carriage diameter-measuring machine is a bench micrometer mounted on a carriage.

PROCEDURE :-

-A calibrated setting cylinder having nearly same diameter as the minor diameter of the thread to be measured is used as setting standard.

-the setting cylinder is held between the V anvils and readings are taken.


-the cylinder is then replaced by the threaded work piece and again the micrometer reading is noted.

If , D= diameter of the setting cylinder,

R1= reading of micrometer on setting cylinder.

R2= reading of micrometer on screw thread.



Then minor diameter of screw thread, = $D \pm (R2-R1)$



03 Marks
Procedure

03 Mark
For sketch

| | | | |
|-----|----|---|---|
| | | | |
| c) | | <p> a = Roughness value R_a in micrometres or = Roughness grade number $N1$ to $N12$. b = Production method, treatment or coating c = Sampling length d = Direction of lay e = Machining allowance f = Other roughness values (in brackets). </p> | <p>03 Mark for sketch</p> <p>03 Mark for labelling</p> |
| Q.6 | a) | <p>Procedure :-</p> <ol style="list-style-type: none"> 1.1 The given work piece is cleaned before taking measurement. 1.2 The fixed blade of the bevel protractor is made to coincide with the reference surface of work piece. 1.3 Move the movable blade of protractor to coincide with outer surface. 1.4 The angle between the blades is taken from protractor after noting main scale and vernier scale reading. <p>Angle between the faces is given by</p> $A = \text{main scale reading} + \text{L.C.} \times (\text{Vernier scale reading})$ <p>Least Count of the Protractor = 5 minute.</p> <p><i>*If sine bar and slip gauge are used then it is also accepted*</i></p> | <p>Procedure 04 Marks and Sketch 02 Marks</p> |

| b) | <table border="1"> <thead> <tr> <th data-bbox="196 140 812 310">Angle gauges</th> <th data-bbox="812 140 1403 310">Slip gauges</th> </tr> </thead> <tbody> <tr> <td data-bbox="196 310 812 411">(i) Angle gauges enables angle to be set to the nearest 3".</td> <td data-bbox="812 310 1403 411">Slip gauges are universally accepted end standard of length in industry.</td> </tr> <tr> <td data-bbox="196 411 812 474">(ii) It has triangular in cross section.</td> <td data-bbox="812 411 1403 474">It has rectangular in cross section.</td> </tr> <tr> <td data-bbox="196 474 812 646">(iii) The angle gauges are marked with engraved V which indicates the direction of the inclined angle which affects on addition and subtraction of angles.</td> <td data-bbox="812 474 1403 646">The direction of slip gauges is not affected in addition and subtraction of dimension.</td> </tr> <tr> <td data-bbox="196 646 812 747">(iv) Angle gauges are available in 12 and 13 pieces set.</td> <td data-bbox="812 646 1403 747">Slip gauges are available in M-45, M-87, M-112 and M-33/2.</td> </tr> <tr> <td data-bbox="196 747 812 877">(v) Any angle can built by adding and subtraction of angle gauges in combination with square block.</td> <td data-bbox="812 747 1403 877">Any linear dimension can built by adding the combination of slip gauges.</td> </tr> </tbody> </table> | Angle gauges | Slip gauges | (i) Angle gauges enables angle to be set to the nearest 3". | Slip gauges are universally accepted end standard of length in industry. | (ii) It has triangular in cross section. | It has rectangular in cross section. | (iii) The angle gauges are marked with engraved V which indicates the direction of the inclined angle which affects on addition and subtraction of angles. | The direction of slip gauges is not affected in addition and subtraction of dimension. | (iv) Angle gauges are available in 12 and 13 pieces set. | Slip gauges are available in M-45, M-87, M-112 and M-33/2. | (v) Any angle can built by adding and subtraction of angle gauges in combination with square block. | Any linear dimension can built by adding the combination of slip gauges. | 1.5 Mark Each |
|--|--|------------------|-------------|---|--|--|--------------------------------------|--|--|--|--|---|--|---------------|
| Angle gauges | Slip gauges | | | | | | | | | | | | | |
| (i) Angle gauges enables angle to be set to the nearest 3". | Slip gauges are universally accepted end standard of length in industry. | | | | | | | | | | | | | |
| (ii) It has triangular in cross section. | It has rectangular in cross section. | | | | | | | | | | | | | |
| (iii) The angle gauges are marked with engraved V which indicates the direction of the inclined angle which affects on addition and subtraction of angles. | The direction of slip gauges is not affected in addition and subtraction of dimension. | | | | | | | | | | | | | |
| (iv) Angle gauges are available in 12 and 13 pieces set. | Slip gauges are available in M-45, M-87, M-112 and M-33/2. | | | | | | | | | | | | | |
| (v) Any angle can built by adding and subtraction of angle gauges in combination with square block. | Any linear dimension can built by adding the combination of slip gauges. | | | | | | | | | | | | | |
| c) i) |  <p align="center">True Running of lathe main spindle</p> | 03 Marks Diagram | | | | | | | | | | | | |
| ii) |  <p align="center">Run out of Spindle</p> | 03 Marks Diagram | | | | | | | | | | | | |